COMMERCIAL WHEEL ALIGNMENT

Limit the damage, reduce the costs.

WHAT YOU SHOULD KNOW

Correctly aligned wheels offer these benefits and cost savings:

Fuel savings

Rolling resistance from the tyre increases if alignment is not correctly adjusted correctly adjusted alignment will reduce fuel consumption and running costs.

Optimised tyre mileage

Incorrect alignment is one of the main causes of tyre wear - 1mm misalignment decreases tyre mileage performance by 7%.

Reduced mechanical wear

When wheels or axles are not aligned, mechanical parts are subject to increased stress and premature wear, for example, suspension components and bearings, increasing vehicle maintenance cost and down time.

Safety improvements

Vehicle handling, safety and driver comfort also depend on the wheel and axle alignment.

TRANSIT

www.lodgetyre.com

Lodge Tyre Co Ltd. Lodge House, Unit E, University Court, Staffordshire Technology Park, Stafford, ST18 OGE, United Kingdom Telephone: 0121 359 2107 Sales: sales@lodgetyre.com Technical support: support@lodgetyre.com

COMMERCIAL WHEEL ALIGNMENT

Better all round performance.

WWW ALCODISET VIREACT

HOUR BREMON

TREAD TEARING

TREAD FEATHERING

SHOULDER DAMAGE

- Excessive wear to the tread area resulting in tearing of tread ribs and/or blocks. Caused by wheel alignment problems on front steer axles.
- Excessive wear across breadth of the tread pattern leading to feathered appearance.
- Commonly found on steer axles of vehicles with steering geometry problems.
- Tyres scrub across the ground instead of rolling freely.
- Related to nearside steer axle of truck generally attributed to under inflation.
- Influenced by steering geometry faults.



- We use professional market leading products.
- Allows easy access to trackrod ends.



- Eliminates rolling the vehicle 'to and fro'.
- Can be used on 4 post lifts, pits or floors.



- Fits wheels from 17"- 24".
- 'Laser' beam enables easy to read measurements.



www.lodgetyre.com

Lodge Tyre Co Ltd. Lodge House, Unit E, University Court, Staffordshire Technology Park, Stafford, ST18 OGE, United Kingdom Telephone: 0121 359 2107 Sales: sales@lodgetyre.com Technical support: support@lodgetyre.com